



Inspection Report

Inspection Date:

#N/A

General Information

Maker	HITACHI
Model Number	ZV550W
Year	2012
Hour (h)	366
Serial Number	10740

Note for External Appearance

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	#N/A
Exhaust Color	Normal
Blow-by	#N/A
Engine Sound	OK
Radiator	Not enough cooling water
Water Pump	#N/A
Injection Pump	#N/A

Note for Control Panel

Note for Engine

Other Information

Admin. No. 3000063159

*This report is only for your reference. We are not responsible for the actual condition of checked item.