



# Inspection Report

Inspection Date: 2024/08/13

## Wheel Loader

### General Information

Maker	HITACHI
Model Number	LX20-7
Year	2005
Hour (h)	2738
Serial Number	HFK4E100H00004637 (F36-04637)

### Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

### Undercarriage

Front Accel	Oil leak
Rear Accel	No oil leak

### Engine

Model	D1503-DI-K2A
Serial Number	05S0454
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

### Documents

Automobile Inspection Certificate	No
-----------------------------------	----

### Note for External Appearance



### Note for Upper Structure



### Note for Operating Component

- With CAB (cabin) heater



### Note for Undercarriage

- Tire size: 12.5/70-16 L-2



### Note for Engine



Admin. No. 3000062460

\*This report is only for your reference. We are not responsible for the actual condition of checked item.