



# Inspection Report


Inspection Date: 2017/10/11

## Excavators


General Information			
Maker	YANMAR		
Model Number	PC30MR-2		
Year	2004		
Hour (h)	968	Meter	Replaced
Serial Number	22315		


Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Big
	Right	N/A	N/A	
Arm		No	No	Big
Bucket		No	No	Big
Bucket Size (mm)		420		


Note for External Appearance
Repainted



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage
The rubber shoes have deteriorated over time and are partly cracked


Engine	
Model	3D84E-5NBA
Serial Number	4112
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
The seat is partly torn


Note for Engine
The battery is flat


Admin No. 2017100756