



Inspection Report

Inspection Date: 2024/03/13

Wheel Loader

General Information

Maker	KOMATSU
Model Number	WA30-6
Year	2010
Hour (h)	1308
Serial Number	KMTWA106A04090801

Note for External Appearance

- The serial plate is missing
- Repainted



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component

- CAB (cabin)
- Without Air conditioner



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine



Admin. No. 3000055713

*This report is only for your reference. We are not responsible for the actual condition of checked item.