



Inspection Report

Inspection Date: 6/28/2016

Excavator

General Information

Maker	KOBELCO
Model Number	SK75UR
Year	2004
Hour (h)	5820
Serial Number	YR0 [REDACTED]

Note for External Appearance

The lower side of the left frame has a dent



Upper Structure

Boom Cylinder (Left)	No oil leak
Boom Cylinder (Right)	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	700
Swing	Backlash and play

Note for Upper Structure

- Equipped with multi lever
- The tip of the arm is bent
- The cover of the boom cylinder is lost
- The boom has a patch



Undercarriage

Swivel Joint	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage

Steel shoes + rubber pads
Oil oozing from the left travel motor



Note for Operating Component

Torn sheet



Engine

Model	4JG1
Serial Number	248617
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Engine

