



Inspection Report

Inspection Date: 2018/12/17


Excavators

| General Information | | | |
|----------------------|---------|--------------|---------|
| Maker | HITACHI | | |
| Model Number | ZX30U-3 | | |
| Year | 2008 | | |
| Hour (h) | 2194 | Meter | Working |
| Serial Number | 20122 | | |

| Options | |
|---------|-----------|
| - CNP | |
| - Blade | - Pipings |
| - EPA | |


| Upper Structure | | | | |
|-------------------------|--------------|----------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | No |
| | Right | N/A | N/A | |
| Arm | | No | No | No |
| Bucket | | No | No | Small |
| Bucket Size (mm) | | 550 | | |

Note for External Appearance
Unable to check its VIN




| Undercarriage | | | |
|------------------------|------------------------------|--------------|--|
| Shoe Type | Steel shoes with rubber pads | | |
| Swing Circle | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 300 | 300 | |
| Idler | OK | NG | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

Note for Upper Structure




Note for Undercarriage
The shoes are loose



| Engine | |
|-------------------------|---------------|
| Model | 3KNPA |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | Normal |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Unchecked |
| Multi Lever | No oil leak |

Note for Operating Component



Note for Engine



Admin No. 2018120102