

Inspection Date: 2017/10/12

General Information		
Maker	YANMAR	
Model Number	ViO40-5	
Year	2005	
Hour (h)	2666 Meter	Working
Serial Number	50758B	

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pipings
- EPA	

Upper Structure					
		Cylinder		Play	
		Oil Leak	Scratch/Rust	ı iay	
Boom -	Left	No	No	Big	
	Right	N/A	N/A	big	
	Arm	No	No	Big	
	Bucket	No	No	Big	
Bucket Size (mm) 560					

Repainted		
	-	

Undercarriage		
Shoe Type	Rubber	
Swing Circle	Oil leak	
	Left	Right
Shoe Width (mm)	350	350
ldler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure	
Oil leak from around the control valve	







