

## **Inspection Report**

Inspection Date: 2019/07/16

## Excavators

General Information			
Maker	YANMAR		
Model Number	ViO30-5		
Year	2006		
Hour (h)	4227 <b>Me</b>	ter	Working
Serial Number	50696B		

### **Upper Structure**

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	Smail
Arm		No	No	Small
Bucket		No	No	Big
Bucket Siz	ze (mm)	520		

## Undercarriage

Undercarnage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	ОК	ОК
Sprocket	ОК	ОК
Pin Bush	ОК	ОК
Upper Roller	ОК	ОК
Track Roller	ОК	ОК
Shoe Link	ОК	ОК

Engine	
Model	3TNV82A-N
Serial Number	36531
Engine Oil Leak	No oil leak
Engine Oil Gauge	ОК
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

## Options - CNP - Speed changer - Multilever - Blade - Pipings - EPA

## Note for External Appearance Repainted




## Note for Upper Structure

1 side of the arm has been reinforced

# Note for Undercarriage

- Note for Operating Component
   Quick hitch
- The seat is partly torn





\*This report is only for your reference. We are not responsible for the actual condition of checked item.