



Inspection Report


Inspection Date: 2018/02/09

Excavators


General Information			
Maker	KOBELCO		
Model Number	SK75UR-3E		
Year	2003		
Hour (h)	4527	Meter	Working
Serial Number	YR06-05758		


Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil leak	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		670		


Note for External Appearance


Undercarriage			
Shoe Type	Rubber		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	440	440	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	NG	OK	
Shoe Link	OK	OK	

Note for Upper Structure
The h link is for arm crane


Note for Undercarriage
- The rubber shoes have deteriorated over time and are partly cracked
- 3 pin bushes of the left rubber shoe are lost


Engine	
Model	CC-4JG1PYA
Serial Number	4JG1-240539
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component


Note for Engine


Admin No. 2018010507