



Inspection Report

Inspection Date: 2016/09/13

Mini Excavator

General Information

Maker	KUBOTA
Model Number	RX503
Year	2003
Hour (h)	5215
Serial Number	103**

Note for External Appearance

Repainted



Upper Structure

Boom Cylinder	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	620
Swing	Backlash and play

Note for Upper Structure

The bucket and arm have plays



Operating Component

Speed Pedal	Yes
-------------	-----

Note for Operating Component



Undercarriage

Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage

Oil oozing from the right lower roller



Engine

Model	V2203
Serial Number	03S1117
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak

Note for Engine



admin No

2016090007

*This report is only for your reference. We are not responsible for the actual condition of checked item.