



# Inspection Report

Inspection Date: 2017/05/11

## Excavators

### General Information

<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK135SR-1ES		
<b>Year</b>	2007		
<b>Hour (h)</b>	5708	<b>Meter</b>	Working
<b>Serial Number</b>	YY04-094**		

### Options

- CAB	
- Multilever	
- Air conditioner	
- Arm Crane	
- EPA	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	890			

### Note for External Appearance

Repainted



### Note for Upper Structure



### Note for Undercarriage



### Undercarriage

<b>Shoe Type</b>	Steel	
<b>Swing Circle</b>	No oil leak	
	Left	Right
<b>Shoe Width (mm)</b>	700	700
<b>Idler</b>	OK	OK
<b>Sprocket</b>	OK	OK
<b>Pin Bush</b>	OK	OK
<b>Upper Roller</b>	OK	OK
<b>Track Roller</b>	OK	OK
<b>Shoe Link</b>	OK	OK

### Note for Operating Component



### Note for Engine



### Shoe Link

<b>Model</b>	BB-4BG1T
<b>Serial Number</b>	946484
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	Oil oozing
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

Admin No. 2017050000