



# Inspection Report

Inspection Date: 2020/10/25

## Motor Grader

### General Information

<b>Maker</b>	KOMATSU
<b>Model Number</b>	GD405A-3E0
<b>Year</b>	2004
<b>Hour (h)</b>	4564
<b>Serial Number</b>	KMTGD002V26006064

### Engine

<b>Model</b>	SAA6D102E-2-A
<b>Serial Number</b>	263564
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	No fuel leak

### Note for External Appearance

- CAB
- A 3.1m blade and scarifier have been installed
- Rear-tire size: 11.00-20 10PLY

### Note for Control Panel

- Mileage: 2051km

### Note for Engine

### Other Information

- Temporarily deregistered

Admin. No. 3000019952

\*This report is only for your reference. We are not responsible for the actual condition of checked item.