Inspection Report

Inspection Date: 2026/11/09

Excavators

General Information

Maker	KUBOTA		
Model Number	U-30-6		
Year	2017		
Hour (h)	4512	**Meter**	Working
Serial Number	21842		

Options

- CNP	- Speed changer
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	**Left**	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		480		

Note for External Appearance

- Repainted
- The body has some scratches and rust



Note for Upper Structure



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	**Right**
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Undercarriage



Engine

Model	D1703
Serial Number	7HW8692
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Unchecked
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component



Note for Engine



Admin No. 3000091514

*This report is only for your reference. We are not responsible for the actual condition of checked item.