



Inspection Report


Inspection Date: 2018/03/18

Excavators


| General Information | | | |
|---------------------|---------|-------|---------|
| Maker | KUBOTA | | |
| Model Number | RX-303S | | |
| Year | 2006 | | |
| Hour (h) | 3550 | Meter | Working |
| Serial Number | 61081 | | |


| Options | |
|--------------|-----------------|
| - CAB | - Speed changer |
| - Multilever | |
| - Blade | |
| - Arm Crane | |

| Upper Structure | | | | |
|------------------|-------|----------|--------------|-------|
| | | Cylinder | | Play |
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | Small |
| Bucket | | No | Yes | Big |
| Bucket Size (mm) | | 430 | | |


| Note for External Appearance |
|---|
|  |

| Undercarriage | | |
|-----------------|------------------------------|-------|
| Shoe Type | Steel shoes with rubber pads | |
| Swing Circle | No oil leak | |
| | Left | Right |
| Shoe Width (mm) | 300 | 300 |
| Idler | OK | OK |
| Sprocket | OK | OK |
| Pin Bush | OK | OK |
| Upper Roller | OK | OK |
| Track Roller | OK | OK |
| Shoe Link | OK | OK |

| Note for Upper Structure |
|---|
|  |

| Note for Undercarriage |
|---|
|  |

| Engine | |
|------------------|---------------|
| Model | D1503-KA |
| Serial Number | 06S0635 |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | No oil leak |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | Unchecked |
| Multi Lever | No oil leak |

| Note for Operating Component |
|---|
| - The seat is partly worn and torn - Heater |
|  |

| Note for Engine |
|---|
|  |

Lot No ARA013-0032 Admin No. 2018030699