



Inspection Report

Inspection Date: 2018/03/12

Wheel Loader

General Information

Maker	KOMATSU
Model Number	WA100-3E
Year	1999
Hour (h)	2348
Serial Number	54527

Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Engine

Model	S4D102E-1
Serial Number	26379450
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Documents

Automobile Inspection Certificate	Yes
--	-----

Note for External Appearance

Canopy



Note for Upper Structure



Note for Operating Component



Note for Undercarriage

Tire size: 16.9-24



Note for Engine



Lot No ARA013-0056

Admin. No. 2018010741

*This report is only for your reference. We are not responsible for the actual condition of checked item.