



Inspection Report

Inspection Date:

Aerial Work Platform

General Information

Maker	SMAC
Model Number	RH120
Year	2008
Hour (h)	3584
Serial Number	00010

Note for External Appearance

- Repainted
- Some tires have some cracks and scratches

Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Other Information

Admin. No. 3000089661

*This report is only for your reference. We are not responsible for the actual condition of checked item.