



Inspection Report

Inspection Date: 2026/02/02

Excavators

General Information

Maker	KUBOTA		
Model Number	U-30-6		
Year	2015		
Hour (h)	2540	Meter	Working
Serial Number	11000		

Options

- CNP
- Multilever
- Blade
- Arm Crane

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		0		

Note for External Appearance

- The covers have some rust and scratches



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- The rubber shoes are cracked and worn



Engine

Model	
Serial Number	7FY3049
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

- The battery is flat



Admin No. 3000087833

*This report is only for your reference. We are not responsible for the actual condition of checked item.