



Inspection Report

Inspection Date: 2017/08/16

Wheel Loader

General Information

Maker	KOMATSU
Model Number	WA350-1
Year	1990
Hour (h)	-
Serial Number	20698

Note for External Appearance



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	Oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure

Oil leak from the pipings of the right lift-arm cylinder (it will be fixed before shipment according to the seller)



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component

Unable to check the hour meter because the monitor panel is damaged



Engine

Model	S6D110-1
Serial Number	63552
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

Tire size: 20.5-25 16PR



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine



Admin. No. 2017080001

*This report is only for your reference. We are not responsible for the actual condition of checked item.