



Inspection Report

Inspection Date: 2018/04/13

Wheel Loader

General Information

Maker	KOMATSU
Model Number	WA30-5E
Year	2002
Hour (h)	1941
Serial Number	23730

Note for External Appearance

Repainted



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component



Engine

Model	3D84E-3DB
Serial Number	40869
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

Note for Undercarriage

Tire size: 12.5 70-16 6 P.R.



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine



Admin. No. 2018040350

*This report is only for your reference. We are not responsible for the actual condition of checked item.