



Inspection Report


Inspection Date: 2023/05/26

Excavators


General Information			
Maker	YANMAR		
Model Number	B6-6A		
Year	2015		
Hour (h)	4508	Meter	Working
Serial Number	67004		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Unchecked
Bucket Size (mm)				


Note for External Appearance



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
- Offset type - No bucket; no H-link - The blade is deformed


Engine	
Model	4TNV88-BXBVD
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Undercarriage
- The rubber shoes are severely cracked and worn


Note for Operating Component


Note for Engine
- Oil leak from the pilot hose


Admin No. 3000050463