



Inspection Report

Inspection Date: 2021/06/04

Excavators

General Information

Maker	KOMATSU		
Model Number	PC200-6		
Year	1993		
Hour (h)	2992	Meter	Working
Serial Number	PC200-81202		

Options

- | | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Big
Bucket Size (mm)		1030		

Note for External Appearance

- No serial plate
- The cover near the left multi lever is partly decayed



Undercarriage

Shoe Type	Steel	
Swing Circle	Oil leak	
	Left	Right
Shoe Width (mm)	600	600
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- The track frames are rusty and decayed



Engine

Model	S6D95L
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000032429