



Inspection Report

Inspection Date: 2024/12/14

Excavators

General Information

Maker	KOMATSU		
Model Number	PC138US-8		
Year	2013		
Hour (h)	6425	Meter	Working
Serial Number	KMTPC189J01030141		


Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	Oil oozing	No	
Arm		Oil oozing	No	Small
Bucket		No	No	Small
Bucket Size (mm)	840			


Note for External Appearance

- Repainted
 - The body has some scratches and rust
 - Cement adheres to some parts of the body
- 

Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The bucket has some cracks
- 

Note for Undercarriage



Engine

Model	SAA4D95LE-5
Serial Number	539684
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000067377