



Inspection Report

Inspection Date: 2018/03/18

Excavators

General Information

Maker	KOMATSU		
Model Number	PC138US-10		
Year	2015		
Hour (h)	1982	Meter	Working
Serial Number	42944		

Options

- CAB
- Multilever
- Speed changer
- Air conditioner
- Pipings

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		890		

Note for External Appearance

Heavier counterweight



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

4 sides of the arm are reinforced



Note for Undercarriage

The rubber pads are severely worn



Engine

Model	SAA4D95LE-6
Serial Number	707068
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- Front guard (ROPS)
- Rear-view camera



Note for Engine

The battery is flat



Lot No ARA013-0002 Admin No. 2018020309