



Inspection Report

Inspection Date: 2024/12/10

Excavators

General Information

Maker	KOMATSU		
Model Number	PC138US-8		
Year	2013		
Hour (h)	5876	Meter	Working
Serial Number	31706		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	850			

Note for External Appearance

- Repainted
- The body has some scratches and rust



Undercarriage

Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	500	500
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The arm has been reinforced
- Some bucket teeth are missing



Note for Undercarriage

- The right sprocket has oil oozing marks



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Not enough cooling water
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000067037