



# Inspection Report

Inspection Date:

## Vibrating Roller

### General Information

<b>Maker</b>	SAKAI
<b>Model Number</b>	HV51ST
<b>Year</b>	
<b>Hour (h)</b>	
<b>Serial Number</b>	5HV20-60559

### Note for External Appearance

### Engine

<b>Model</b>	E75-E3-NB
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Radiator</b>	OK
<b>Water Pump</b>	Unchecked
<b>Injection Pump</b>	Unchecked

### Note for Control Panel

### Note for Engine

### Other Information

- The vibrator works properly

Admin. No. 3000065509

\*This report is only for your reference. We are not responsible for the actual condition of checked item.