



Inspection Report

Inspection Date: 2019/03/26


Excavators

General Information			
Maker	KOBELCO		
Model Number	SK75UR-3ES		
Year	2007		
Hour (h)	4790	Meter	Working
Serial Number	YR07-07290		

Options	
- CAB	- Air conditioner
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		670		


Note for External Appearance



Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- Rotation is not smooth
- The arm has been reinforced




Note for Undercarriage



Engine	
Model	CC-4JG1PYA-01
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

The seat is partly torn



Note for Engine



Admin No. 2019030437