

936EZ Wheel Loader/Backhoe Loader

BASIC INFORMATION

Inspection Date		Model	936EZ	Serial No.	4SB02032
Date of Manufacture		Hourmeter	4952 HR	Condition of Hourmeter	HR is normal
Hourmeter (Estimated)		Mileage		Engine No.	
Job Status	Other	Accident History		License Number Plate	None
Cabin/Canopy	Cabin	Cabin Type	Standard	Power Transmission System	Torque Converter
Drive System	All Wheel Drive	Size of Tire	20.5-25-16PR	Type of Tire	Spike
Bucket/Attachment	Loading BK	Stamp		Others	Cooler

OPERATION

Engine	Normal	Exhaust Gas Color	Normal	Traveling	Normal
Transmission/Torque Converter	Normal	Clutch	Normal	HST Motor	
Front Section	Normal	Pump Device	Normal	Steering	Normal
Break	Normal	Side Break	Normal	Swing	
Outrigger					

UNDERCARRIAGE/CHASSIS/TIRES

Scratches: Tire(Front-Right Wheel)	Moderate	Wear: Tire(Front-Right wheel)	Moderate	Scratches: Tire(Front-Left Wheel)	Moderate
Wear: Tire(Front-Left Wheel)	Moderate	Scratches: Tire(Rear-Right Wheel)	Moderate	Wear: Tire(Rear-Right Wheel)	Moderate
Scratches: Tire(Rear-Right Wheel)	Moderate	Wear: Tire(Rear-Left Wheel)	Moderate	Oil Leak: Axle	No
Oil Leak: Differential Gear Case	No				

FRONT & PINS

Lift Arm	Normal Standards	Bellcrank	Normal	Wear: Front Pins and Bushings	Moderate/Within Service Limit ステアリング操作時、車体左右のガタ振れは有り(どこからのガタかは不明)。
Wear: Bucket Pins and Bushings	Moderate/Within Service Limit	Wear: Center Pins	Moderate/Within Service Limit	Wear: Bucket Side Plate	Moderate/Within Service Limit
Wear: Bucket Lip	Moderate/Within Service Limit	Wear: Bucket Bottom Plate	Moderate/Within Service Limit	Wear: Tooth/Cutting Edges	Moderate/Within Service Limit

OIL/WATER/AIR LEAK

Oil Leak: Front Pipes	No	Oil Leak: Lift Cylinder(Right)	No	Oil Leak: Lift Cylinder(Left)	No
Oil Leak: Bucket Cylinder	No	Oil Leak: Steering Cylinder	Slight Film	Oil Leak: Tilt Cylinder	
Oil Leak: Angle Cylinder(Right)		Oil Leak: Angle Cylinder(Left)		Oil Leak: Swing Cylinder	
Oil Leak: Outrigger Cylinder		Oil Leak: Engine	Moderate Oozing	Oil Leak: Oil Cooler	No
Leak: Radiator	No	Leak: Cooling Pipes	No	Oil Leak: Fuel System	Slight Film
Compressor	Normal	Oil Leak: Control Valve	Slight Film	Oil Leak: Low Pressure Pipes	No
Oil Leak: High Pressure Pipes	Moderate Oozing	Oil Leak: Pilot Pipes	No	Oil Leak: Pilot Valve	No
Oil Leak: Pump Device	No	Oil Leak: Transmission/Torcon	Moderate Oozing		

APPEARANCE

Main frame	Rusted/Corroded	Front Frame	Rusted/Corroded	Counter Weight	Scratched, Rusted/Corroded
Cabin/Canopy	Rusted/Corroded	Door	Good Condition		

INTERIOR

Cabin Interior	Good Condition	Seat	Torn	Console	Malfunction, Missing FUELメーター、一定しない(フラフラしている)。
Air conditioner	Malfunction 温度調整ダイヤル、少ししか回らない。	Freon gas inspection	Good Condition		

BACKHOE

Oil Leak: Boom Cylinder		Oil Leak: Arm Cylinder		Oil Leak: Bucket Cylinder	
-------------------------	--	------------------------	--	---------------------------	--

OVERALL RATING

Appearance Evaluation	Fair	Rust/Corrosion	Moderate	Overall Rating	Fair
Special Notes					