



Inspection Report


Inspection Date: 2018/05/17

Excavators


General Information			
Maker	KOBELCO		
Model Number	SK75UR-3E		
Year			
Hour (h)	8465	Meter	Working
Serial Number	YR05-05533		


Options	
- CAB	- Air conditioner
- Multilever	
- Blade	
- Arm Crane	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	Unchecked	Unchecked	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		680		


Note for External Appearance
Repainted


Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	-	-
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
- The offset has play
- Rotation is not smooth
- Arm crane movement is unchecked


Note for Undercarriage


Engine	
Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
The seat has been repaired


Note for Engine


Admin No. 2018050419