



# Inspection Report

Inspection Date: 2019/03/11

## Generator

### General Information

<b>Maker</b>	DENYO
<b>Model Number</b>	DCA-15SPK
<b>Year</b>	
<b>Hour (h)</b>	4914
<b>Serial Number</b>	2891193

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	Oil oozing
<b>Engine Oil Gauge</b>	OK
<b>Exhaust Color</b>	Unchecked
<b>Blow-by</b>	Unchecked
<b>Engine Sound</b>	Unchecked
<b>Radiator</b>	Rust/Oil
<b>Water Pump</b>	No water leak
<b>Injection Pump</b>	Fuel oozing

### Note for External Appearance

The upper part of the body has some dents

### Note for Control Panel

- Operational conditions are unchecked
- According to the seller, the engine and the generator work properly

### Note for Engine

- The battery is flat
- Operational conditions of the engine and the generator are unchecked

Admin. No. 2019030014

\*This report is only for your reference. We are not responsible for the actual condition of checked item.