



Inspection Report

Inspection Date: 2022/11/12

Excavators

General Information

Maker	KOMATSU		
Model Number	PC78US-8		
Year	2014		
Hour (h)	2264	Meter	Working
Serial Number	KMTPC213JEA028781		

Options

- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)	645			

Note for External Appearance



Undercarriage


Shoe Type	Steel	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- Some of the right and left shoes have kinks



Engine

Model	SAA4D95LE-5
Serial Number	558746
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000043661