



Inspection Report

Inspection Date: 2018/10/25

Wheel Loader

General Information

Maker	MITSUBISHI
Model Number	WS300A
Year	
Hour (h)	3836
Serial Number	5WA00315

Note for External Appearance

The body is partly rusty



Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

Note for Upper Structure



Undercarriage

Front Accel	No oil leak
Rear Accel	No oil leak

Note for Operating Component

The seat is partly torn



Engine

Model	
Serial Number	11014
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	Unchecked

Note for Undercarriage



Documents

Automobile Inspection Certificate	No
--	----

Note for Engine



Admin. No. 2018100236

*This report is only for your reference. We are not responsible for the actual condition of checked item.