



Inspection Report

Inspection Date: 2023/12/22

Excavators

General Information

Maker	KUBOTA		
Model Number	U-30-6		
Year	2016		
Hour (h)	2817	Meter	Working
Serial Number	11094		

Options

- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	465			

Note for External Appearance

- The right cover is detached
- The body has some dents



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	300	300	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage



Engine

Model	
Serial Number	7GA3897
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine

- Oil oozing from control valve



Admin No. 3000052208