



# Inspection Report

Inspection Date: 2026/03/02

## Wheel Loader

### General Information

Maker	KOMATSU
Model Number	WA40-8
Year	2019
Hour (h)	65
Serial Number	KMTWA133CKE075016

### Upper Structure

Lift Arm Cylinder (Left)	No oil leak
Lift Arm Cylinder (Right)	No oil leak
Bucket Cylinder (Left)	No oil leak
Bucket Cylinder (Right)	No oil leak

### Undercarriage

Front Accel	Oil oozing
Rear Accel	Oil oozing

### Engine

Model	4D88E-7PAA
Serial Number	63011
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Water Pump	No water leak
Radiator	OK

### Documents

Automobile Inspection Certificate	No
-----------------------------------	----

### Note for External Appearance

- Repainted



### Note for Upper Structure



### Note for Operating Component

- The hour meter might be replaced  
- A/C



### Note for Undercarriage



### Note for Engine



Admin. No. 3000082549

\*This report is only for your reference. We are not responsible for the actual condition of checked item.