

Inspection Report

Mini Excavator

General Information	
Maker	KOMATSU
Model Number	PC28UU-3
Year	2005
Hour (h)	4077
Serial Number	321**

Upper Structure	
Boom Cylinder	No oil leak
Arm Cylinder	No oil leak
Bucket Cylinder	No oil leak
Bucket Width (mm)	420
Swing	Backlash and play

Operating Component

Speed Pedal Yes

Undercarriage		
Swing Circle	Oil oozing	
	Left	Right
Shoe Width (mm)	295	295
Idler	NG	NG
Sprocket	OK	ОК
Pin Bush	OK	ОК
Upper Roller	ОК	ОК
Track Roller	OK	ОК
Shoe Link	ОК	ОК

Engine	
Model	3D82AE-3HB
Serial Number	18294
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	ОК
Exhaust Color	Normal
Blow-by	No
Engine Sound	ОК
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil cooler

Note for External Appearance

Repainted Frame dent



Note for Upper Structure

Boom and offset and arm and bucket have plays



Note for Operating Component

Multi lever

Note for Undercarriage

Note for Engine

white smoke out in heavy burden



admin No

2016090259

*This report is only for your reference. We are not responsible for the actual condition of checked item.