



Inspection Report

Inspection Date: 2024/12/02

Excavators

General Information

| | | | |
|----------------------|------------|--------------|---------|
| Maker | KOBELCO | | |
| Model Number | SK80UR-6 | | |
| Year | 2014 | | |
| Hour (h) | 4573 | Meter | Working |
| Serial Number | YR10-10576 | | |

Options

| | |
|--------------|-------------------|
| - CAB | - Speed changer |
| - Multilever | - Air conditioner |
| - Blade | |
| - Arm Crane | |

Upper Structure

| | | Cylinder | | Play |
|------------------|-------|------------|--------------|-------|
| | | Oil Leak | Scratch/Rust | |
| Boom | Left | No | No | Small |
| | Right | N/A | N/A | |
| Arm | | No | No | Small |
| Bucket | | Oil oozing | No | Big |
| Bucket Size (mm) | 670 | | | |

Note for External Appearance

- The body has some scratches



Undercarriage

| | | | |
|---------------------|------------------------------|--------------|--|
| Shoe Type | Steel shoes with rubber pads | | |
| Swing Circle | No oil leak | | |
| | Left | Right | |
| Shoe Width (mm) | 450 | 450 | |
| Idler | OK | OK | |
| Sprocket | OK | OK | |
| Pin Bush | OK | OK | |
| Upper Roller | OK | OK | |
| Track Roller | OK | OK | |
| Shoe Link | OK | OK | |

Note for Upper Structure



Note for Undercarriage



Engine

| | |
|-------------------------|---------------|
| Model | |
| Serial Number | |
| Engine Oil Leak | No oil leak |
| Engine Oil Gauge | OK |
| Radiator | OK |
| Exhaust Color | Normal |
| Blow-by | No |
| Engine Sound | OK |
| Hydraulic Pump | Oil oozing |
| Water Pump | No water leak |
| Oil Cooler | No oil leak |
| Motor | No oil leak |
| Multi Lever | No oil leak |

Note for Operating Component



Note for Engine



Admin No. 3000066793