



Inspection Report


Inspection Date: 2018/04/13

Excavators


General Information			
Maker	KUBOTA		
Model Number	U-008		
Year	2007		
Hour (h)	1995	Meter	Working
Serial Number	18367		


Options	
- Multilever	- Speed changer
- Blade	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		300		


Note for External Appearance
Repainted



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	180	180
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The edges of the bucket sides are bent


Note for Undercarriage
The rubber shoes have deteriorated over time and are worn


Engine	
Model	D722
Serial Number	7N1712
Engine Oil Leak	Oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Black/Gray
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
Fuel leak from the lower part of the engine stop solenoid


Note for Engine
Black smoke comes out when idling


Admin No. 2018040323