



Inspection Report

Inspection Date: 2026/07/18

Excavators

General Information

#ERROR!	KUBOTA		
Model Number	U-20-3		
Year	2013		
Hour (h)	4002	Meter	Working
Serial Number	15701		

Options

- CNP	- Speed changer
- Multilever	
- Blade	- Pippings

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	No	No	
Arm		Oil oozing	No	Small
Bucket		No	No	Small
Bucket Size (mm)		400		

Note for External Appearance

- Repainted
- The body has some scratches and rust



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- The bucket is corroded
- No bucket teeth



Note for Undercarriage



Engine

Model	D1105
Serial Number	1DT2738
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 3000087698

*This report is only for your reference. We are not responsible for the actual condition of checked item.