



Inspection Report

Inspection Date: 2024/07/20

Excavators

General Information

Maker	KUBOTA		
Model Number	U-20-3S		
Year	2010		
Hour (h)	2578	Meter	Working
Serial Number	12600		

Options

- CNP	- Speed changer
- Multilever	
- Blade	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	400			

Note for External Appearance

- Repainted



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	250	250
Idler	NG	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

--



Note for Undercarriage

--




Engine

Model	D1105
Serial Number	AG3937
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn
- The right travel lever is slightly stiff



Note for Engine

--



Admin No. 3000061034