



Inspection Report


Inspection Date: 2018/06/28

Excavators


General Information			
Maker	YANMAR		
Model Number	B6-6A		
Year	2008		
Hour (h)	5712	Meter	Working
Serial Number	62139B		


Options	
- CNP	- Speed changer
- Multilever	- Air conditioner
- Blade	
- Arm Crane	
- EPA	

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)		620		


Note for External Appearance



Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure


Note for Undercarriage


Engine	
Model	3NNP
Serial Number	A5081
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component
- The seat is partly torn - The seat has been fixed


Note for Engine
The engine speed decreases under load


Admin No. 2018061644