



Inspection Report

Inspection Date: 2018/05/16


Excavators

General Information			
Maker	KOBELCO		
Model Number	SK200-6E		
Year	2004		
Hour (h)	10254	Meter	Working
Serial Number	YN09-35932		

Options	
- CAB	- Speed changer
- Multilever	- Air conditioner
	- Pipings


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	No	No	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		1030		

Note for External Appearance
- The body has some scratches
- The counterweight has some dents




Undercarriage			
Shoe Type	Steel		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	600	600	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure
- The arm has some dents
- 5 piping




Note for Undercarriage
- The shoes are loose
- The right shoe plates are partly damaged



Engine	
Model	6D34-TLU2D
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component
- The seat has some holes
- The air conditioner is broken



Note for Engine



Admin No. 2018050415