



Inspection Report

Inspection Date: 2023/09/03

Excavators

General Information

Maker	KUBOTA		
Model Number	U-30-5		
Year	2007		
Hour (h)	5282	Meter	Working
Serial Number	70410		

Options

- | | |
|--------------|-----------------|
| - CNP | - Speed changer |
| - Multilever | |
| - Blade | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	Small
Bucket Size (mm)		420		

Note for External Appearance

- No VIN plate



Undercarriage

Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	300	300
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure

- No bucket side cutters
- The upper structure gradually drops by itself



Note for Undercarriage

- Oil oozing from the left travel motor
- The rubbers have some cracks



Engine

Model	D1703EDM
Serial Number	07Q1781
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

- The seat is torn



Note for Engine



Admin No. 3000051052

*This report is only for your reference. We are not responsible for the actual condition of checked item.