



# Inspection Report

Inspection Date: 2019/02/22

## Excavators

General Information			
<b>Maker</b>	KOBELCO		
<b>Model Number</b>	SK13SR		
<b>Year</b>			
<b>Hour (h)</b>	2165	<b>Meter</b>	Working
<b>Serial Number</b>	PE01-02193		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Breaker Pipings

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		360		

**Note for External Appearance**



Undercarriage			
<b>Shoe Type</b>	Steel shoes with rubber pads		
<b>Swing Circle</b>	Unchecked		
	Left	Right	
<b>Shoe Width (mm)</b>	230	230	
<b>Idler</b>	OK	OK	
<b>Sprocket</b>	OK	OK	
<b>Pin Bush</b>	OK	OK	
<b>Upper Roller</b>	OK	OK	
<b>Track Roller</b>	OK	OK	
<b>Shoe Link</b>	OK	OK	

**Note for Upper Structure**  
Operational condition of the upper structure is unchecked



**Note for Undercarriage**  
- Oil leak from the right travel motor pipes  
- Traveling motion is unchecked



Engine	
<b>Model</b>	3TNE68-EYB
<b>Serial Number</b>	D1528
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	Unchecked
<b>Exhaust Color</b>	Unchecked
<b>Blow-by</b>	Unchecked
<b>Engine Sound</b>	Unchecked
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	Unchecked
<b>Multi Lever</b>	No oil leak

**Note for Operating Component**  
True hour unknown



**Note for Engine**  
Operational condition of the engine is unchecked



Admin No. 2019020522