



# Inspection Report

Inspection Date:

## Attachment

### General Information

<b>Maker</b>	KOMATSU
<b>Model Number</b>	JTHB40-3
<b>Year</b>	2013
<b>Hour (h)</b>	
<b>Serial Number</b>	10311

### Note for External Appearance

### Engine

<b>Model</b>	
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	#N/A
<b>Engine Oil Gauge</b>	#N/A
<b>Exhaust Color</b>	#N/A
<b>Blow-by</b>	#N/A
<b>Engine Sound</b>	#N/A
<b>Radiator</b>	#N/A
<b>Water Pump</b>	#N/A
<b>Injection Pump</b>	#N/A

### Note for Control Panel

### Note for Engine

- Pin diameter: 4.5mm
- Center width: 17mm

### Other Information

Admin. No. 3000058694

\*This report is only for your reference. We are not responsible for the actual condition of checked item.