



Inspection Report

Inspection Date: 2026/09/12

Excavators

General Information

Maker	KOMATSU		
Model Number	PC45MR-5N0		
Year	2019		
Hour (h)	3850	Meter	Working
Serial Number	33055		

Options

- CAB	- Speed changer
- Blade	- Air conditioner
- EPA	

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	No	No	
Arm		Oil oozing	No	Small
Bucket		No	No	Small
Bucket Size (mm)		510		

Note for External Appearance



Undercarriage

Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	NG	NG
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure



Note for Undercarriage

- The shoes have some kinks
- The rubber pads are deteriorated; some rubber pads are missing



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	-

Note for Operating Component



Note for Engine



Admin No. 3000089441

*This report is only for your reference. We are not responsible for the actual condition of checked item.