



# Inspection Report

Inspection Date: 2024/11/30

## Excavators

### General Information

<b>Maker</b>	YANMAR		
<b>Model Number</b>	VIO70-3A		
<b>Year</b>	2011		
<b>Hour (h)</b>	3711	<b>Meter</b>	Working
<b>Serial Number</b>	36229		

### Options


- CAB	- Speed changer
- Multilever	- Air conditioner
- Blade	

### Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	No	Small
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	No	Big
Bucket Size (mm)	650			

### Note for External Appearance

- The frame is rusty
- The right cover is detached



### Undercarriage

<b>Shoe Type</b>	Steel shoes with rubber pads	
<b>Swing Circle</b>	No oil leak	
	Left	Right
Shoe Width (mm)	450	450
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK


### Note for Upper Structure

--



### Note for Undercarriage

- Oil oozing from the lower rollers
-------------------------------------



### Engine

<b>Model</b>	3TNWA
<b>Serial Number</b>	
<b>Engine Oil Leak</b>	No oil leak
<b>Engine Oil Gauge</b>	OK
<b>Radiator</b>	OK
<b>Exhaust Color</b>	Normal
<b>Blow-by</b>	No
<b>Engine Sound</b>	OK
<b>Hydraulic Pump</b>	No oil leak
<b>Water Pump</b>	No water leak
<b>Oil Cooler</b>	No oil leak
<b>Motor</b>	No oil leak
<b>Multi Lever</b>	No oil leak

### Note for Operating Component

--



### Note for Engine

--



Admin No. 3000066780