



Inspection Report

Inspection Date: 2025/12/17

Excavators

General Information	
Maker	YANMAR
Model Number	B4-6A
Year	2011
Hour (h)	5243
Meter	Working
Serial Number	65056B

Options	
- CNP	- Speed changer
- Multilever	
- Blade	
- Arm Crane	
- EPA	

Upper Structure			
		Cylinder	
		Oil Leak	Scratch/Rust
Boom	Left	No	No
	Right	No	No
Arm	Oil oozing	No	Small
Bucket	No	No	Big
Bucket Size (mm)	540		

Note for External Appearance	
- Repainted	
- The body has some scratches and rust	

Undercarriage		
Shoe Type	Rubber	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	350	350
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure	
	

Engine	
Model	3TNV88-BQBVD
Serial Number	F4447
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	Oil oozing

Note for Operating Component	
- The seat is torn	

Note for Engine	
- Unusual noise from the fan belt or muffler when accelerating at high speed.	

Admin No. 3000079841

*This report is only for your reference. We are not responsible for the actual condition of checked item.