



Inspection Report

Inspection Date:

Aerial Work Platform

General Information

Maker	AICHI
Model Number	SR21A
Year	2007
Hour (h)	7517
Serial Number	714406

Note for External Appearance

- Repainted
- The body is rusty

Engine

Model	4JG1
Serial Number	343555
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Radiator	OK
Water Pump	No water leak
Injection Pump	No fuel leak

Note for Control Panel

Note for Engine

Other Information

- The crawler has a kink partly

Admin. No. 3000087926

*This report is only for your reference. We are not responsible for the actual condition of checked item.