



Inspection Report

Inspection Date: 2018/09/23

Excavators

General Information

Maker	KOMATSU		
Model Number	PC78UU-6E0		
Year	2005		
Hour (h)	5634	Meter	Working
Serial Number	25061		

Options

- | | |
|-------------|-------------------|
| - CAB | - Speed changer |
| - Blade | - Air conditioner |
| - Arm Crane | |

Upper Structure

		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	No
	Right	N/A	N/A	
Arm		No	No	Small
Bucket		No	Yes	Big
Bucket Size (mm)	640			

Note for External Appearance

Repainted



Undercarriage

Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
		Left	Right
Shoe Width (mm)			
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	OK	OK	
Shoe Link	OK	OK	

Note for Upper Structure



Note for Undercarriage

Oil oozing from the right travel motor and the reduction drive



Engine

Model	
Serial Number	
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Normal
Exhaust Color	Normal
Blow-by	No
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component

Unable to check the arm crane movement because there is no battery



Note for Engine

No battery



Admin No. 2018090342