



Inspection Report

Inspection Date: 2018/12/20

Excavators


General Information			
Maker	YANMAR		
Model Number	VIO40-5B		
Year	2011		
Hour (h)	3848	Meter	Working
Serial Number	57177B		

Options	
- CNP	- Speed changer
- Multilever	
- Blade	- Pipings

Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	No	No	Small
	Right	No	No	
Arm		No	No	Small
Bucket		No	No	Small
Bucket Size (mm)		565		

Note for External Appearance

- The body is partly repainted
- The covers have deteriorated over time




Undercarriage			
Shoe Type	Steel shoes with rubber pads		
Swing Circle	No oil leak		
	Left	Right	
Shoe Width (mm)	350	350	
Idler	OK	OK	
Sprocket	OK	OK	
Pin Bush	OK	OK	
Upper Roller	OK	OK	
Track Roller	NG	NG	
Shoe Link	OK	OK	

Note for Upper Structure




Note for Undercarriage

- Oil oozing from 2 of the left and right lower rollers
- The rubber pads have deteriorated over time and are worn



Engine	
Model	4TNB88-B
Serial Number	68965
Engine Oil Leak	No oil leak
Engine Oil Gauge	OK
Radiator	Black/Gray
Exhaust Color	Black/Gray
Blow-by	No
Engine Sound	OK
Hydraulic Pump	Oil oozing
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	No oil leak
Multi Lever	No oil leak

Note for Operating Component



Note for Engine



Admin No. 2018120173