



Inspection Report

Inspection Date: 2018/03/15


Excavators

General Information			
Maker	KUBOTA		
Model Number	U-40-3S		
Year	2006		
Hour (h)	4710	Meter	Working
Serial Number	30785		

Options	
- CNP	- Breaker Pippings
- Multilever	
- Blade	


Upper Structure				
		Cylinder		Play
		Oil Leak	Scratch/Rust	
Boom	Left	Oil oozing	Scratch	No
	Right	N/A	N/A	
Arm		No	No	No
Bucket		No	No	No
Bucket Size (mm)		550		

Note for External Appearance
- A new canopy will be attached before shipment
- Repainted




Undercarriage		
Shoe Type	Steel shoes with rubber pads	
Swing Circle	No oil leak	
	Left	Right
Shoe Width (mm)	400	400
Idler	OK	OK
Sprocket	OK	OK
Pin Bush	OK	OK
Upper Roller	OK	OK
Track Roller	OK	OK
Shoe Link	OK	OK

Note for Upper Structure
The boom cylinder has some scratches




Note for Undercarriage
The rubber pads have deteriorated over time and are partly worn




Engine	
Model	V2203
Serial Number	06C0074
Engine Oil Leak	Oil oozing
Engine Oil Gauge	OK
Radiator	OK
Exhaust Color	Normal
Blow-by	Yes
Engine Sound	OK
Hydraulic Pump	No oil leak
Water Pump	No water leak
Oil Cooler	No oil leak
Motor	Unchecked
Multi Lever	No oil leak

Note for Operating Component



Note for Engine
Oil oozing from the engine near the water pump



Lot No ARA013-0047 Admin No. 2018030499